



## Software Release Note for STA

Product Name	USB Wireless Card
Interface Supported	USB
Install Package Version	MT7610U_D5.0.1.23_SDK1.0.2.15_UI5.0.0.22_20150210.dmg
Driver Version	5.0.1.23
User Interface Version	5.0.0.22
Date	2015-02-10

**System Requirement:**

Mac OS X 10.10.X / 10.9.X / 10.8.X /10.7.X

**Hardware Supported:**

MT7610U chipset USB

MT7612U chipset USB

**Software Supported:**

Mac OS X 10.10.X / 10.9.X / 10.8.X /10.7.X

USBWireless-Install.pkg

© 2014 MediaTek Inc.

This document contains information that is proprietary to MediaTek Inc.

Unauthorized reproduction or disclosure of this information in whole or in part is strictly prohibited.

Specifications are subject to change without notice.

## Release History:

### **Driver 5.0.1.23**

1. 7662 WiFi MAC CR value update.

### **Driver 5.0.1.22**

1. Fixed Rssi issue.

### **Driver 5.0.1.21**

1. Fixed Scan no AP issue

### **Driver 5.0.1.20**

1. Fixed disconnect issue after few hours
2. Update Firmware

### **Driver 5.0.1.19**

1. Fixed disconnect issue after few hours
2. WDOG setting change

### **Driver 5.0.1.14**

3. Support EDCCA
4. Support DFS

### **Driver 5.0.1.13**

1. WiFi Mac Initial CR update

### **Driver 5.0.1.12**

1. Support set and query Country Region
2. Support DFS

### **Driver 5.0.1.11**

1. Some code does not include VHT for Phy is A Band capable  
Use macro as each PHY combination ex. IS\_PHY\_SUPPORT\_5G\_ONLY  
Remove PHY\_11A check and only use RadarChannelCheck for DFS

### **Driver 5.0.1.10**

1. Support EDCCA

